Jamie Kennedy

From: Anstey, Jonathan P. < Jon. Anstey@terracon.com>

Sent: Monday, August 15, 2016 10:23 AM

To: Jamie Kennedy

Subject: 100SP DMR - July 2016

Attachments: 2016-07 DMR Page 2.pdf; 2016-07 DMR Page 1.pdf

Jamie,

AUG 16 2016

Overly Control Please find attached the July 2016 Discharge Monitoring Report for the 100 Saint Paul building for your review and signature. There were no exceedances during the month and flow has continued to be fairly steady at 33.69 gallons per minute. Based on first weeks of August, the flow may be decreasing as precipitation decreases. Let me know if you need additional information or an updated summary table.

Please submit the original signed DMR pages to the address below and send me a scan copy for my files.

Colorado Department of Public Health and Environment Water Quality Control Division WQCD-P-B2 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Thanks,

Jonathan P. Anstey, P.G. **Senior Project Geologist I Environmental**

Terracon

10625 West I-70 Frontage Road North, Suite 3 I Wheat Ridge, Colorado 80033 D (303) 454-5202 | F (303) 423-3353 | M (720) 201-6105 ipanstey@terracon.com | terracon.com

Join us on Facebook and LinkedIn

(5) Please consider the environment before printing this email (6)

For the latest Terracon news, subscribe to our RSS Feed

Terracon provides environmental, facilities, geotechnical, and materials consulting engineering services delivered with responsiveness, resourcefulness, and reliability.

Private and confidential as detailed here (www.terracon.com/disclaimer). If you cannot access hyperlink, please e-mail sender.